



Bulletin #: 0051 Manufacturer: All Vehicle: All

Service: Power Steering Service

Call Tech Support for Ex-Rite Faults

COMPLAINT: Ex-Rite power steering fluid exchange machine stops working

properly.

CAUSE: Multiple possibilities.

CORRECTION: Go through the Troubleshooting section of your Operating Manual.

Never take the back off your machine! If you can't get the system working by following the procedure in your Troubleshooting section, call Customer Support at 800-872-8921 and we'll handle

your situation.