



CAT Products, Inc

Technical Service Bulletin

Bulletin #: 0053
Manufacturer: All
Vehicle: All
Service: Power Steering Service

Position the Wand Properly During Ex-Rite Power Steering Service

- COMPLAINT:** Ex-Rite service draws air into the power steering system.
- CAUSE:** Ex-Rite wand may be positioned too low, drawing air into the system. This may cause stiff steering until the air bleeds out of the fluid.
- CORRECTION:** When performing a power steering fluid exchange, always position wand so that fluid remains in reservoir.

