

Technical Service Bulletin

Bulletin #: 0021
Manufacturer: All
Vehicle: All

Service: Fuel and Induction System

Use Caution When Servicing Hybrids or Dual-Fuel Engines

Run-Rite fuel system service procedures are safe and effective for the gasoline component in today's hybrid vehicles, and on dualfuel engines.

However, there are specific safety issues with hybrids. The orange wires are part of a high voltage system that controls the electric motor/generators that drive the vehicle. These systems develop voltages over 300 volts in some cases.

Never service these vehicles unless you're comfortable with these systems. Improper or careless service procedures can damage the vehicle or cause serious injury.

CAT Products, Inc. will accept no liability for any damage or injury caused by technicians who are unfamiliar with these systems or are careless under the hood.

When servicing dual-fuel engines, always follow the procedures provided for gas-only vehicles.

