



CAT Products, Inc

Technical Service Bulletin

Bulletin #: 0006
Manufacturer: All
Vehicle: All
Service: Fuel and Induction System

Keep Your BLAST Tool Dry and Working Like New

COMPLAINT: BLAST nozzle becomes clogged.

CAUSE: Moisture in your shop air lines.

CORRECTION: Install a water separator/filter in the air line. Drain the separator and replace the filter and desiccant regularly to keep the compressed air dry and clean.

For additional information, refer to the BLAST operating manual, page 10.

