



CAT Products, Inc

Technical Service Bulletin

Bulletin #: 0018
Manufacturer: All
Vehicle: All
Service: Fuel and Induction System

Protect Plastics and Painted Surfaces from Throttle Body Cleaner

COMPLAINT: Paint or plastic damage caused by TBC spray.

CAUSE: TBC is more caustic than other fuel system cleaners, and can damage plastic, rubber, or painted surfaces.

CORRECTION: Avoid spraying TBC on any plastic, rubber, or painted surfaces. If necessary, use a shield to prevent overspray from reaching these surfaces.

And never let the TBC puddle when cleaning the throttle body. Use a clean shop towel to absorb any leftover spray when cleaning the throttle body.

