



CAT Products, Inc

Technical Service Bulletin

Bulletin #: 0026
Manufacturer: Nissan
Vehicle: All w/Drive-by-Wire
Service: Fuel and Induction System

Don't Clean the Throttle Body on Drive-by-Wire Nissans

- COMPLAINT:** Trouble code sets after a fuel and induction cleaning service on Nissans with drive-by-wire (electronic throttle control, or ETC).
- CAUSE:** The throttle body cleaning solution works into the drive-by-wire controller.
- CORRECTION:** Avoid the problem entirely: Don't perform a throttle body cleaning on any Nissan equipped with drive-by-wire throttle control.

